

DATE – 24/4/17

# SCHEDULE OF ISSUES OUTSIDE REMIT OF TASKFORCE

PARISH – Burton Agnes

OFFICER – Paula Parker

ROAD	ELEMENT				LOCATION/DETAILS	COMMENTS
Main Street	C'Way Pothole		Signage		Junction with Rudston Road – Burton Agnes Hall sign blocking visibility – private land – Photo 1	25/4/17 Email sent to planning enforcement
	F'Way Pothole		Sweeping			
	Painting		Other	x		
Main Street	C'Way Pothole		Signage		2 x sunken drains outside Holme View Barn & 1 Holme View. Concern over noise when lorries pass over sunken area. VTF to attempt some filling, engineer comment. Photo's 2 & 3	
	F'Way Pothole		Sweeping			
	Painting		Other	x		
Station Road	C'Way Pothole		Signage		Outside Tanya – crumbling & sinking footpath – photo 4. Engineer to comment.	
	F'Way Pothole	x	Sweeping			
	Painting		Other			
Station Road	C'Way	x	Signage		Deteriorating carriageway/numerous potholes. TF to attempt temporary fix. Engineer to comment. Photo 5	
	F'Way Pothole		Sweeping			

	Painting	Other			
Station Road	C'Way Pothole	Signage		After Brickworks Cottage. Blocked gully. Referred to Steve Roberts, engineer. Photo 6	
	F'Way Pothole	Sweeping			
	Painting	Other	x		
	C'Way Pothole	Signage			
	F'Way Pothole	Sweeping			
	Painting	Other			
	C'Way Pothole	Signage			
	F'Way Pothole	Sweeping			
	Painting	Other			